

FUSION PLUG-IN HYB

ALTO BLUE METALLIC TC INTERIOR **EBONY LEATHER-TRIMMED**

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

• DRVR SIDEVIEW MIR-AUTO DIM EASY FUEL® CAPLESS FILLER

ford.com

- FOG LAMPS-LED
- GLASS SOLAR-TINTED
- HEADLAMP COURTESY DELAY **HEADLAMPS-LED**
- MIRRORS HTD/PWR/MAN-FOLD TURN SIG/APPRCH LAMP/MEM
- **REAR SPOILER**
- TAIL LAMPS LED
- TIRE INFLATOR/SEALANT KIT

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

FRONT LICENSE PLATE BRACKET

EQUIPMENT GROUP 850A

2020 MODEL YEAR ALTO BLUE METALLIC TC

50 STATE EMISSIONS

WIPERS - RAIN-SENSING

INTERIOR

AMBIENT LIGHTING

2.0L IVCT I4 HEV

 AUTO-DIM REARVIEW MIRROR DUAL-ZONE ELECTRONIC **AUTO CLIMATE CONTROL**

2020 FUSION PLUG-IN HYB TI 5-PASSENGER

ECVT AUTO TRNS POWERSPLIT

ROTARY GEAR SHIFT DIAL

(MSRP)

395.00

NO CHARGE

NO CHARGE

- SEATS-HTD/CLD, 10-WAY PWR **DRV & 6-WAY PWR PASS**
- SMART CHARGING USB PORT(2)
- STEERING WHEEL PREMIUM **LEATHER-WRAPPED HEATED**
- WINDOWS-1-TOUCH UP/DOWN FRONT/REAR

FUNCTIONAL


- ACTIVE NOISE CONTROL
- AUDIO SPEAKERS-12
- FORD CO-PILOT360™ • INTELLIGENT ACCESS W/PUSH **BUTTON START**
- MYFORD® MOBILE
- REAR VIEW CAMERA
- REVERSE SENSING SYSTEM

SAFETY/SECURITY

- AIRBAG-DRIVER/PASS KNEE
- AIRBAGS DUAL STAGE FRONT AIRBAGS - FRONT SEAT

LR 171934

- MOUNTED SIDE IMPACT
- AIRBAGS SIDE AIR CURTAIN
- LATCH CHILD SAFETY SYSTEM • PERIMETER ALARM
- SECURILOCK® ANTI-THEFT SYS



Crash

Side

Crash

Rollover


Passenger

Front seat

Rear seat

Based on the risk of injury in a side impact

Based on the risk of rollover in a single-vehicle crash





Not Rated

Not Rated

Not Rated









Insist on Ford Protect! The only extended service

plan fully backed by Ford and honored at every Ford dealership in the U.S., Canada and Mexico. See your Ford dealer or visit www.FordOwner.com.

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead. which are known to the State of California to cause cancer and birth defects or other reproductive harm To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

www.safercar.gov or 1-888-327-4236

3FA6P0SU6LR171934





www.ford.com/help/privacy-terms/

SCAN OR TEXT 3FLR171934 TO 48028

RAMP ONE **RD27** RAIL RAMP TWO

ITEM #:

This label is affixed pursuant to the Federal Automobile

State and Local taxes are not included. Dealer installed

Information Disclosure Act. Gasoline, License, and Title Fees,

options or accessories are not included unless listed above.

72-2245 O/T 2

FORD CREDIT

TOTAL MSRP

TOTAL SAVINGS

Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.

\$36,390.00

LA171 N RA 2X 035 001286 01 17 20