KAN-001257 _{CA}	9-NORMAL, NB, 201257, JM142 86	220181222 3837	ULC U R C. CERT CERT CERT TRD RAMP BU	A C MP CAMP BOOK EXFL
VEHI	CLE DESCRIPTION 5-150 2019 F-150 4X4 SUPERCREW 145" WHEELBASE 5.0L V8 ELEC 10-SPEED AUTO W/TOW	EXTERIOR OXFORD W INTERIOR V MO V MO EUNCTIONAL • AUTO START STOP TECH • CURVE CONTROL • DYNAMIC HITCH ASSIST • ELECT 4X4 SHIFT-ON-FLY • ELECTRIC-ASSIST PARK BRAKE • FAIL-SAFE COOLING SYSTEM • FORDPASS'** CONNECT 4GW HOTSPOT TELEMATICS MODEM • GAS-CHARGED SHOCKS • MYKEY® • OUTBOARD MNTD REAR SHOCI • PRE-COLLISION ASSIST W/AEB • REAR VIEW CAMERA • SELECTSHIFT® • SYNC®3 W/8" TOUCHSCREEN • PRICE IN BASE PRI TOTAL OF	CERT CERT CERT TRD RAMP BUI KK C39891 KK C39891 MITE RAY CLOTH 40/20/40 SAFETY/SECURITY ADVANCETRAC® WITH RSC® AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® CTR HIGH MOUNT STOP LAMP PERIMETER ALARM IFORMATION SOS POST-CRASH ALERT SYS™ STR/60,000 BUMPER / BUMPER SYR/60,000 ROADSIDE ASSIST	MP CAMP BOOK EXFL FILE FUE Fuel Economy Fuel Economy Standard Pi Fuel Economy MPGe. Val. Combined city/hwy Gity Combined Combined Combined City/hwy Gity Combined Combined Combined City/hwy Gity Combined Combined Compared to other vehicles of similar size of thould ONLY be compared to
	RAMP ONE	тот	AL MSRP \$46,405.00	Rollover★ ★Based on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (★ ★ ★ ★), wi Source: National Highway Traffic Safety Admini www.safercar.gov or 1-888-327-41FTEW1E57KKC39891
	CB76		Whether you decide to lease or finance your	
	RAMP TWO	CONVOY 72-A04E O/T 9Z FORD CRED	vehicle, you'll find the choices that are right for you. See your dealer for details or visit	WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine e
	This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not in options or accessories are not	the Federal Automobile Isoline, License, and Title Fees, Icluded. Dealer installed JM142	www.ford.com/finance. SPECIAL ORDER N RB 2XX 915 001257 12 14 18	lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

2201812223837

01/22/2020

