Year: 2018 Make: MINI Model: Hardtop 2 Door FWD VIN: WMWXP5C59J2G63166

MECHANICAL

- · Front-Wheel Drive
- · 3.42 Axle Ratio
- · 80-Amp/Hr Maintenance-Free Battery w/Run Down Protection
- · 150 Amp Alternator
- · Gas-Pressurized Shock Absorbers
- Front And Rear Anti-Roll Bars
- Electric Power-Assist Speed-Sensing Steering
- · 10.6 Gal. Fuel Tank
- · Single Stainless Steel Exhaust
- w/Polished Tailpipe Finisher
- · Strut Front Suspension w/Coil
- Springs

Multi-Link Rear Suspension w/Coil Springs

- EXTERIOR
- · Steel Spare Wheel
- · Compact Spare Tire Mounted Inside
- Under Cargo
- · Clearcoat Paint
- · Body-Colored Front Bumper
- · Body-Colored Rear Bumper
- · Black Fender Flares
- · Chrome Side Windows Trim,
- Chrome Front Windshield Trim and Chrome Rear Window Trim
- · Chrome Door Handles
- Body-Colored Power Heated Side Mirrors w/Manual Folding
- · Fixed Rear Window w/Fixed Interval
- Wiper and Defroster
- Light Tinted Glass
- · Speed Sensitive Rain Detecting Variable Intermittent Wipers
- w/Heated Jets
- · Fully Galvanized Steel Panels
- · Black Grille w/Chrome Surround
- · Liftgate Rear Cargo Access
- · Perimeter/Approach Lights

ENTERTAINMENT

- · 6 Speakers
- · Audio Theft Deterrent
- · Integrated Roof Diversity Antenna

INTERIOR

 \cdot 6-Way Driver Seat -inc: Manual Recline, Height Adjustment, Fore/Aft Movement and Manual Rear Seat Easy Entry

- 6-Way Passenger Seat -inc: Manual Recline, Fore/Aft Movement and Manual Rear Seat Easy Entry
- · 60-40 Folding Bench Front Facing
- Fold Forward Seatback Rear Seat
- · Manual Tilt/Telescoping Steering Column
- · Fixed Rear Windows
- · Front Cupholder
- · Rear Cupholder
- · Power Fuel Flap Locking Type

Dual Zone Front Automatic Air Conditioning

- HVAC -inc: Underseat Ducts
 Illuminated Glove Box
- · Driver Foot Rest
- · Full Cloth Headliner
- · Leatherette Gear Shifter Material

· Interior Trim -inc: Metal-Look Instrument Panel Insert, Metal-Look Door Panel Insert and Chrome/Metal-

- Look Interior Accents
- Day-Night Rearview Mirror
 Driver And Passenger Visor Vanity
 Mirrors w/Driver And Passenger

Illumination and Driver Auxiliary Mirror

• Full Floor Console w/Storage, Mini Overhead Console and 1 12V DC Power Outlet

- · Front Map Lights
- · Fade-To-Off Interior Lighting
- · Full Carpet Floor Covering -inc:
- Carpet Front And Rear Floor Mats
- Carpet Floor Trim
 Rigid Cargo Cover
- Rigid Cargo Cover
- Cargo Space Lights
 MINI 6.5" Visual Boost Screen
- Covered Dashboard Storage,
- Refrigerated/Cooled Box Located In The Glovebox, Driver And Passenger
- Door Bins
- Power 1st Row Windows w/Driver And Passenger 1-Touch Up/Down
- Delayed Accessory Power
- Systems Monitor
- Outside Temp Gauge
- · Analog Appearance
- Front Center Armrest w/Storage
- · 2 Seatback Storage Pockets
- · Seats w/Leatherette Back Material
- · Manual Adjustable Front Head
- Restraints and Manual Adjustable Rear
- Head Restraints
- · 1 12V DC Power Outlet
- Air Filtration

SAFETY

- · Side Impact Beams
- · Dual Stage Driver And Passenger
- Seat-Mounted Side Airbags
- · Rear Parking Sensors
- Low Tire Pressure Warning • Dual Stage Driver And Passenger Front Airbags
- · Curtain 1st And 2nd Row Airbags
- · Airbag Occupancy Sensor
- Driver And Passenger Knee Airbag
- Outboard Front Lap And Shoulder
- Safety Belts -inc: Pretensioners

MonroneyLabels.com

· Back-Up Camera

Engine: 3 Cylinder Engine Transmission: 6-SPEED MANUAL

New

MSRP

INSTALLED OPTIONS

Style 495

Tires: 195/55R16

Heated Front Seats

Original Shipping Charge

[258] Runflat Tires

[A94] Midnight Black Metallic

[ZSG] Signature Line Package

White Turn-Signal Lights Wheels: 16" x 6.5" Victory Spoke Black

Transmission: 6-Speed Automatic w/STEPTRONIC

RETAIL PRICE (ORIGINALLY NEW)

Get more information on your

smartphone:

California Motors

Direct - Fontana

fontanamotorsdirect.com 909-895-4370

Colors: Midnight Black metallic (A94) / Black Leatherette Mileage: 17,847 Stock #: J2G63166





HIGHWAY MPG

\$21.100.00

\$500

\$0

\$850

\$24,650.00

\$2,200

Actual mileage will vary with options, driving conditions, driving habits and vehicle's condition